



FOWLER PRODUCTS COMPANY

PROVIDING SOLUTIONS FOR THE PACKAGING REQUIREMENTS OF INDUSTRY

150 Collins Industrial Blvd.
P.O. Box 80268 Athens, GA 30608-0268 USA
PHONE: (706) 549-3300 • FAX: (706) 548-3583

www.fowlerproducts.com

TECHNICAL SERVICE BULLETIN

REBUILDING OF HEADS AND HEAD SLIDES

As part of your annual preventative maintenance, Fowler/Zalkin capping heads and head slides should be rebuilt every twelve months. Fowler Products can assist you with this by:

- Providing technical support, assistance, and training to your employees during service visits.
- Rebuilding these components as part of a scheduled Preferred Service Contract Agreement visit.
- Rebuilding heads and head slides at our facility.

Fowler Products is delighted to offer head and head slide rebuilding by trained maintenance personnel at our facility. Many customers install their spare head and head slide on their machine and return the removed components to our factory to be rebuilt. We will disassemble, inspect and replace all normal-wear or damaged components. This proactive approach ensures a minimum amount of production down time and allows you to control your maintenance schedule.

CLEANING OF CAPPING CHUCKS

Capping chucks should be cleaned every 400 hours of use with a clean cloth (free of mineral grease) slightly damp if necessary. Disassemble chuck if necessary. Lubricate with PARALIQ GA 343 as specified in the capping head section in your manual.

SORTER SHIELD MISALIGNMENT

Improper alignment of the sorter's stainless steel shield to the sorter disk can cause aluminum particles to contaminate your product. Though this is rare and is caused by gross maladjustment, check the alignment of the disc and ensure that there is enough clearance that the sorter disk does not rub against any part of the sorters stainless steel shield.

For a quote on spare parts please contact Glenn Nix at 706-549-3300 X-161
To schedule a service visit please contact Earl Benton at 706-549-3300 X-142

For more information on our Preferred Service Contract Agreement and our Evaluation and Training Service Visits, please see our TSB-3 or view all our service bulletins at <http://www.fowlerproducts.com/Service%20Bulletins.htm>